

FIG. 2




FIG. 4




FIG. 5





FIG. 6






FIG. 8




FIG. (

TIMING CHART OF SCANNING X





FIG. 10






FIG. 12




FIG. 1







FIG. 14












FIG. 17







FIG. 1















FIG. 21












FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30





FIG. 31



(STRESS APPLICATION CONDITION)
Vg WAVEFORM: DUTY RATIO OF COMPENSATION SIGNAL
APPLICATION TIME IS FIXED TO 1/10
NO LIGHT EMISSION
STRESS TIME 15min

(Iphoto MEASUREMENT CONDITION)
Vg=-10V
Vsd=1V
LIGHT EMISSION 1000Ix

FIG. 32




FIG. 33

